

Yamada Bulletin

No. 2016-07

DISCONTINUE OF CE-124P PUMP DRIVER

Overview

Manufacturing of CE-124P pump driver have been discontinued

Subjected Items

Model No.	Model
804947	CE-124P Pump Driver
684215	Extension Sensor Cord 2.5M

Replacement Model

Replacement model will be introduced in September 2016

Thank you very much for your long-term patronage of the model.

Please contact intl@yamadacorp.co.jp for further information.