

Yamada Bulletin


Changes in the Pilot Valve Assembly of NDP-40/NDP-50

Thank you for your continuous support to YAMADA.

We would like to inform you that the pilot valve assembly (832162) for NDP-40/NDP-50 (except for NDP-50FAN/ NDP-40-E series/ NDP-50-E series) has been changed in two ways as follows;

(1) Packing Material:


The grade of TPEE, which is the raw material, has been changed in order to improve the oil resistance. Accordingly, the color of the packing has changed from black to white, as the following pictures say.



(2) Shape of Packing:

The shape of the packing has been changed as the following drawings, so that the packing will not be easily removed.

Cross section of packing



The new pilot valve assembly will be supplied from September 2023.

Please note the part number 832162 will be the same. Also please be informed the new parts are interchangeable for the old one.